

MINISTRY OF PUBLIC UTILITIES AND AVIATION

MARITIME ADMINISTRATION DEPARTMENT

NOTICE TO MARINERS

No. 024 (2026) Guyana

DEMERRA RIVER


Maritime Administration Department wishes to inform all Mariners plying the Demerara River that twenty eight (28) Navigational Marker Beacons were reconstructed from Georgetown to Linden.

The Navigational Markers characteristics are as follows:

No.	NAME (LOCATION)	POSITION Latitude N Longitude W ° ' '	CHARACT ER & PERIOD	H.T ABOVE H.W.M (metres)	VIS IN MLS	STRUCTURE	REMARKS
C	DEMERRA						
01.	Navigational Marker C (Ruimveldt)	06 058 47.568 10.251		8.42		Steel Framework tower	Re-established Unlit
02.	Navigational Marker 7 (Friendship)	06 058 40.331 11.240	FL RWG	12.18	6	Steel Framework on 4 Pile wooden Platform	Re-established
03.	Navigational Marker 8 (Chantilly)	06 058 38.036 12.507	FL RWG	10.95	6	Steel Framework on 4 Pile wooden Platform	Re-established
04.	Navigational Marker 10 (Inver Island)	06 058 36.638 12.886	FL RWG	10.35	6	Steel Framework on 4 Pile wooden Platform	Re-established
05.	Navigational Marker 11 (Soesdyke)	06 058 32.462 14.408	FL RWG	11.28	6	Steel Framework on 4 Pile wooden Platform	Re-established
06.	Navigational Marker 13 (Lana)	06 058 29.492 17.399	FL RWG	10.64	6	Steel Framework on 4 Pile wooden Platform	Re-established
07.	Navigational Marker 15 (New Hanover)	06 058 28.792 18.444	FL RWG	10.64	6	Steel Framework on 4 Pile wooden Platform	Re-established
08.	Navigational Marker 16 (Princess Carolina)	06 058 28.687 18.818	FL R 4 sec	10.64	4	Steel Framework on 4 Pile wooden Platform	Re-established
09.	Navigational Marker 18 (Vreed en Rust)	06 058 27.434 18.922	FL R 4 sec	10.06	4	Steel Framework on 4 Pile wooden Platform	Re-established Unlit
10.	Navigational Marker 21 (Low Wood)	06 058 27.434 18.922	FL G 4 sec	10.35	4	Steel Framework on 4 Pile wooden Platform	Re-established Unlit

No.	NAME (LOCATION)	POSITION Latitude N Longitude W ° ' '		CHARACT ER & PERIOD	H.T ABOVE H.W.M (metres)	VIS IN MLS	STRUCTURE	REMARKS
C	DEMERA							
11.	Navigational Marker 24 (Stena)	06 058	22.375 18.898	FL 4 sec	R	10.35	4	Steel Framework tower
12.	Navigational Marker 25 (Susannah's Rust)	06 058	20.625 18.640	FL	RWG	10.64	6	Steel Framework on 4 Pile wooden Platform
13.	Navigational Marker 31 (Dora)	06 058	16.625 16.064	FL	G	10.64	4	Steel Framework on 4 Pile wooden Platform
14.	Navigational Marker 32 (St. Jan)	06 058	16.989 16.103	FL	R	10.35	4	Steel Framework on 4 Pile wooden Platform
15.	Navigational Marker 35 (Clemwood)	06 058	15.462 16.365	FL	G	11.28	4	Steel Framework on 4 Pile wooden Platform
16.	Navigational Marker 38 (Yaruni Island)	06 058	12.615 18.064	FL	R	10.64	4	Steel Framework on 4 Pile wooden Platform
17.	Navigational Marker 39 (Loo Lands)	06 058	12.597 17.957	FL	G	11.28	4	Steel Framework on 4 Pile wooden Platform
18.	Navigational Marker 40 (Yaruni Island)	06 058	12.514 18.050	FL 4 sec	R	10.64	4	Steel Framework on 4 Pile wooden Platform
19.	Navigational Marker 49 (Adventure)	06 058	08.371 15.495	FL 4 sec	G	10.35	4	Steel Framework on 4 Pile wooden Platform
20.	Navigational Marker 50 (De Adventure)	06 058	08.594 15.621	FL 4 sec	R	10.35	4	Steel Framework on 4 Pile wooden Platform
21.	Navigational Marker 51 (Dalgan)	06 058	06.659 16.098	FL 4 sec	G	10.35	4	Steel Framework on 4 Pile wooden Platform
22.	Navigational Marker 52 (Amsterdam)	06 058	05.836 17.045	FL 4 sec	R	10.64	4	Steel Framework on 4 Pile wooden Platform
23.	Navigational Marker 54 (Amsterdam)	06 058	05.281 17.745	FL 4 sec	R	10.64	4	Steel Framework on 4 Pile wooden Platform
24.	Navigational Marker 60 (Lot Nos. 48 & 49)	06 058	03.865 18.142	FL	RWG	10.64	4	Steel Framework on 4 Pile wooden Platform
25.	Navigational Marker 62 (Christian- burg)	06 058	02.973 17.831	FL 4 sec	R	10.64	4	Steel Framework on 4 Pile wooden Platform

No.	NAME (LOCATION)	POSITION Latitude N Longitude W ° °	CHARACT ER & PERIOD	H.T ABOVE H.W.M (metres)	VIS IN MLS	STRUCTURE	REMARKS
C	DEMERA						
26.	Navigational Marker 63 (Amelia's Ward)	06 058 02.322 17.352	FL G 4 sec	11.28	4	Steel Framework on 4 Pile wooden Platform	Re-established
27.	Navigational Marker 65 (Lot 42)	06 058 01.881 17.442	FL RWG	11.28	6	Steel Framework on 4 Pile wooden Platform	Re-established
28.	Navigational Marker 66 (Christian- burg)	06 058 01.496 17.914	FL RWG	11.28	6	Steel Framework on 4 Pile wooden Platform	Re-established



Inset of Chart BA 527 showing Location of Sunken Vessel

This information supersedes information provided on pages 41- 44 in the Tide Tables & List of Lights 2026.

Inset area is included for further guidance.

Communication can be made to the Georgetown Lighthouse, on VHF Ch. 16.

L Baird
Harbour Master (Ag)
For Director General

January 12, 2026