

# MARITIME ADMINISTRATION DEPARTMENT

## NOTICE TO MARINERS

No.105 (2021) Guyana

### APPROACHES TO DEMERARA RIVER AND ESSEQUIBO RIVER

The *Maritime Administration Department (MARAD)* wishes to advise that five (5) **Aids to Navigation** were established at the Approaches to the Demerara and Essequibo River; and along the Essequibo River.

The characteristics of these Aids to Navigations are as follows:

No.	NAME LOCATION	POSITION Latitude N Longitude W ° '	CHARACTER & PERIOD	H.T ABOVE H.W.M (metres)	VIS IN MLS	STRUCTURE	REMARKS
<b>B</b>	<b>ESSEQUIBO</b>						
01.	Wreck "Captain Ricardo"	07 02.375 058 11.564	Fl Q YB	1.83	4	Yellow & Blue Vertically Striped Buoy with Top mark	Established
02.	Naamryck Shoal	06 52.481 058 25.967	Fl Q G	1.83	4	Green Buoy	Established
03.	Grit Shoal	06 41.746 058 35.225	Fl 6 sec R	1.83	4	Red Buoy	Established
04.	Calf Island Shoal	06 26.642 058 36.141		2.50		Red Buoy with Conical Top mark	Established
<b>C</b>	<b>DEMERARA</b>						
05.	Demerara Light	06 56.825 058 03.434	Fl 6 sec R	3.50	10	Red Buoy with Radar Reflector	Re- established

This information supersedes information provided on **Pages 34 & 37** of **2021 List of Lights** and information provided in **Nav Warnings 57 & 58** of **2021**.

Communication can be made to the Georgetown Lighthouse on VHF Ch. 16.

G Archer  
**Harbour Master (Ag)**  
*For Director General*

**September 10, 2021**