

MARITIME ADMINISTRATION DEPARTMENT

NOTICE TO MARINERS

No.127 (2021) Guyana

APPROACHES TO THE WAINI RIVER MOUTH

The *Maritime Administration Department (MARAD)* wishes to advise that three (3) **Aids to Navigation** were established at the Approaches to the Waini River; and along the North West Coast of Guyana.

The characteristics of these Aids to Navigations are as follows:

No.	NAME LOCATION	POSITION Latitude N Longitude W	CHARACTER & PERIOD	H.T ABOVE H.W.M (metres)	VIS IN MLS	STRUCTURE	REMARKS
A	NORTHWEST & POMEROON						
01.	Waini Pt. Beacon (U) (Waini Outer Buoy)	08 28.000 059 47.600	Fl R 5 Sec	1.83	4	Red Buoy	Established
02.	Waini Rear Buoy	08 23.700 058 49.700	Fl R 6 sec	1.83	4	Red Buoy	Established
03.	Wreck "Shivita 2"	08 27.974 059 47.572	Fl W Q	1.83	4	Isolated Danger Mark with Radar Reflector	Established

This information supersedes information provided on **Pages 33** of the **Tide Tables and 2021 List of Lights**

Communication can be made to the Georgetown Lighthouse on VHF Ch. 16.

G Archer
Harbour Master (Ag)
For Director General

October 17, 2021