

MARITIME ADMINISTRATION DEPARTMENT

NOTICE TO MARINERS

No.42 (2022) Guyana

BERBICE RIVER

The *Maritime Administration Department (MARAD)* wishes to advise all vessels operating within the Berbice Main Ship Channel or approaches to the New Amsterdam Harbours that the below mentioned Aid to Navigation (**Beacons**) has been reconstructed.

The characteristics of this Aid to Navigations were as follows:

No.	NAME LOCATION	POSITION Latitude N Longitude W	CHARACTER & PERIOD	H.T ABOVE H.W.M (metres)	VIS IN MLS	STRUCTURE	REMARKS
D	BERBICE						
01.	Rear (Bar)	06 20.200 058 31.800	Fl W 1.5 sec	18.5	20	White steel frame on concrete 6 pile platform	Re-Established Leading Lights Line 216° (T)
02.	Rear (Crab Island)	06 22.400 058 31.200	Fl W 1.5 sec	12	9	Double Wooden Pile with White Metal Top Structure	Operable } Leading Lights 003° (T)
03.	Front (Crab Island)	06 21.700 058 31.300	Fl W Q	9.5	9	Double Wooden Pile with White Metal Top Structure	Operable

This information supersedes information provided on **Pages 40 of the 2022 List of Lights.**

Communication can be made to the Georgetown Lighthouse on VHF Ch. 16.

G Archer
Harbour Master (Ag)
For Director General

January 21, 2022